


TO-252






°C)	(
		~	
		~	
		θ	



			°C			
			°C			
			°C			
			°C			

μ






单位: mm

Symbol	Dimensions In Millimeters		Symbol	Dimensions In Millimeters	
	Min	Max		Min	Max
A	2.20	2.40	E	5.95	6.25
b	0.35	0.25	e1	2.24	2.34
b	0.50	0.70	e2	4.43	4.73
b1	0.64	0.53	L1	9.45	9.95
C	0.45	0.55	L2	1.25	1.75
D	6.45	6.75	L3	0.60	0.90
D1	5.10	5.50	K	0.00	0.10

TO-252



BR
5100

5100

