







单位: mm

Symbol	Dimensions In Millimeters		Symbol	Dimensions In Millimeters	
	Min	Max		Min	Max
A	2.20	2.40	B	0.95	1.25
B	0.95	1.25	b	0.70	0.90
b	0.70	0.90	b1	0.45	0.55
b1	0.45	0.55	C	1.50	2.00
C	1.50	2.00	D	6.45	6.75
D	6.45	6.75	D1	6.10	6.30
D1	6.10	6.30	e1	9.85	10.35
e1	9.85	10.35	e2	15.00	15.50
e2	15.00	15.50	L3	3.00	3.50
L3	3.00	3.50	k1	0.60	0.90
k1	0.60	0.90			

T0-252



